TROPICAL ATMOSPHERE-OCEAN (TAO) PROGRAM FINAL CRUISE REPORT

KA-10-01

Area: Equatorial Pacific between 8°N and 8°S latitude along 155°W Longitude and 8°S to 8°N

Latitude along 170°W Longitude.

Itinerary:

KA-10-01 DEP January 5, 2010, Honolulu, HI

ARR January 21, 2010, Apia, Samoa DEP January 25, 2010, Apia Samoa

ARR February 11, 2010, Kwajalein, RMI

CRUISE DESCRIPTION

The Tropical Atmosphere Ocean (TAO) array consists of 70 buoys utilizing a taut line mooring configuration used to mount data collection sensors for climate research purposes. Fifteen buoys are serviced by JAMSTEC and the remaining 55 buoys from 95°W longitude to 165°E longitude are serviced by National Data Buoy Center (NDBC). Repair and maintenance of the buoys is performed by NDBC contracted personnel on an annual basis utilizing the NOAA Ship *Ka'imimoana* and other ships. The buoys' deployment lifecycle are up to 18 months to ensure at least one year of data collection can be completed.

TAO Project Points of Contact:

TAO Program Manager TAO Operations Manager

Shannon McArthur Lex LeBlanc

National Data Buoy Center National Data Buoy Center

Building 1007 Building 3203

Stennis Space Center, MS 39529 Stennis Space Center, MS 39529

228-688-2830 228-688-7465

Email: shannon.mcarthur@noaa.gov Email: lex.leblanc@noaa.gov

TAO Cruise Objective and Plan:

The objective of this cruise was the maintenance of the TAO Array along the 155°W and 170°W meridians.

The scientific complement for the cruise embarked at *Honolulu*, *HI* on *January 4*, 2010. The ship departed on *January 5*, 2010 and conducted operations as listed in Section 2.1. A short port call at *Apia Samoa* was made *January 21 – 25*, 2010. The ship arrived in *Kwajalein*, *RMI* on *February 11*, 2010.

1.0 **PERSONNEL**

1.1 CRUISE LEAD AND PARTICIPATING SCIENTISTS:

Cruise Lead: Brian Lake, Leg 1 and Dr. Richard Crout, Leg 2

Participating Scientists:

Name	Gender	Nationality	Affiliation
Brian Lake, Leg 1	M	US	NOAA/NDBC
Dr. Richard Crout, Leg 2	M	US	NOAA/NDBC
James Rauch, Legs 1 and 2	M	US	NOAA/NDBC
Alan Lossett, Legs 1 and 2	M	US	NOAA/NDBC

2.0 **OPERATIONS**

2.1 TAO Data Recovery Summary

Mooring Operations conducted are shown in the tables below. The following provides details on the data recovery efforts for the buoys serviced. All noted time in the summary reports is Coordinated Universal Time (UTC):

Cruise Summary

Buoy Site: 8N 155W, ATLAS	Mooring Depth: 5243 m
Mooring Operation: Visit	Mooring ID#: PM810A
Deployed Location: 07 58.72 N 154 59.96W	Deployed Date: 5/9/2009
Visit Location: 07 58.7N 155 00.1W	Visit Date: 1/9/2010

Previous Repair Date: None
Sensors/Equipment Lost at Sea: None
Sensors Damaged/Fouled: None.
Fishing/Vandalism: None
General Comments: Visit only. Buoy riding well in the water. Ship's TSG and RH sensors not recording to SCS.

Buoy Site: 8N 155W, Refresh	Mooring Depth: 5237 m	
Mooring Operation: Refresh Deployment	Mooring ID#: DM006A	
Deployed Location: 07 54.9N 154 57.9W	Deployed Date: 1/9/2010	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 5N 155W, A	ATLAS	Mooring Depth: 4593	3 m
Mooring Operation: F	Recovery	Mooring ID#: PM811	IA
Deployed Location: 0	5 00.3N 154 55.6W	Deployed Date: 5/10/	09
Recovered Location: (04 59.95N 154 55.01W	Recovered Date: 1/10	0/2010
Previous Repair Date:	None		
Sensors/Equipment L	ost at Sea: T200, SN 13	892	
Sensors Damaged/Fou	iled: SSC fouled		
Fishing/Vandalism: N	Vone		
Sensors/Tubes Not Do	wnloaded: All sensors s	successfully downloaded	with the exception of
T25, SN 12662 – no co	mmunications.		
General Comments: 1	None.		
Site Sensor Failures	Date Sensors Failed	Why Sensors Failed	Field Service Observations

Buoy Site: 5N 155W, ATLAS	Mooring Depth: 4603 m	
Mooring Operation: Deployment	Mooring ID#: PM866A	
Deployed Location: 05 00.3N 154 54.5W	Deployed Date: 1/11/2010	
Pre-Deployment On Deck Instrument Failures:	None.	
Sensors/Equipment Lost at Sea: None.		
Sensors Damaged During Deployment: None.		
General Comments: Routine deployment.		

Buoy Site: 2N 155W, ATLAS	Mooring Depth: 4663 m
Mooring Operation: Visit	Mooring ID#: PM812A

Deployed Location: 01 59.17N 154 57.7W	Deployed Date: 5/12/2009	
Visit Location: 01 59.3N 154 58.2W	Visit Date: 1/12/2010	
Previous Repair Date: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None.		
Fishing/Vandalism: None		
General Comments: Visit only. Buoy riding well in the water.		

_

			Observations
Site Sensor Failures	Date Sensors Failed	Why Sensors Failed	Field Service
haulback.			
General Comments: I	nitial problems releasing	the mooring. Anchor rel	leased during
T150, SN 13926 – flooded.			
Sensors/Tubes Not Downloaded: All sensors successfully downloaded with the exception of			
Fishing/Vandalism: N	lone		
Sensors Damaged/Fou	led: SSC, T25, T50 fou	led.	
Sensors/Equipment Lo	ost at Sea: None.		
Previous Repair Date:	None		
Recovered Location: (00 00.2N 154 58.7W	Recovered Date: 1/1	2/2010
Deployed Location: 0	0 00.63N 154 58.19W	Deployed Date: 8/15	/08
Mooring Operation: R	Recovery	Mooring ID#: PM75	8A
Buoy Site: 0 155W, A7	ΓLAS/CO2	Mooring Depth: 465	6 m

Buoy Site: 0 155W, ATLAS	Mooring Depth: 4647 m	
Mooring Operation: Deployment	Mooring ID#: PM867A	
Deployed Location: 00 00.28N 154 57.3W	Deployed Date: 1/13/2010	
Pre-Deployment On Deck Instrument Failures: None.		
Sensors/Equipment Lost at Sea: None.		
Sensors Damaged During Deployment: None.		
General Comments: Fishing vessel ~1.5 nm away from buoy upon deployment. Failed to		
communicate with said vessel (Spanish speaking).		

Buoy Site: 2S 155W, ATLAS	Mooring Depth: 4897 m	
Mooring Operation: Visit	Mooring ID#: PM813A	
Deployed Location: 01 58.34S 154 59.57W	Deployed Date: 5/14/2009	
Visit Location: 01 58.5S 155 00.7W	Visit Date: 1/14/2010	
Previous Repair Date: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None.		
Fishing/Vandalism: None		
General Comments: Visit only. Buoy riding well in the water.		

Buoy Site: 5S 155W, A	ATLAS	Mooring Depth: 502	28 m
Mooring Operation: R	Recovery	Mooring ID#: PM76	60A
Deployed Location: 0	4 59.39S 154 58.29W	Deployed Date: 8/17	7/08
Recovered Location:	04 59.0S 154 59.6W	Recovered Date: 1/1	15/2010
Previous Repair Date:	11/29/2009		
Sensors/Equipment Lo	ost at Sea: T200, SN 13	892	
Sensors Damaged/Fou	iled: SSC, T25 fouled		
Fishing/Vandalism: N	lone		
Sensors/Tubes Not Do	wnloaded: All sensors	successfully downloaded	with the exception of
T150, SN 14175 and T200, SN 14176 – no communications.			
General Comments: 7	Γop 3 shackles missing c	otter pins, top 2 shackles	missing their retaining
nut.			
Site Sensor Failures	Date Sensors Failed	Why Sensors Failed	Field Service
			Observations

Buoy Site: 5S 155W, ATLAS	Mooring Depth: 5038 m	
Mooring Operation: Deployment	Mooring ID#: PM868A	
Deployed Location: 04 58.8S 154 58.0W	Deployed Date: 1/16/2010	
Pre-Deployment On Deck Instrument Failures: None.		
Sensors/Equipment Lost at Sea: None.		
Sensors Damaged During Deployment: None.		
General Comments: Routine deployment.		

Buoy Site: 8S 155W, ATLAS	Mooring Depth: 5307 m	
Mooring Operation: Visit	Mooring ID#: PM814B	
Deployed Location: 08 15.86S 154 59.53W	Deployed Date: 11/29/2009	
Visit Location: 08 16.4S 154.59.3W	Visit Date: 1/9/2010	
Previous Repair Date: None.		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None.		
Fishing/Vandalism: None		
General Comments: Visit only. Buoy riding well in the water.		

Buoy Site: 8S 170W, ATLAS	Mooring Depth: 5371 m	
Mooring Operation: Deployment	Mooring ID#: PM869A	
Deployed Location: 07 59.24N 170 01.118W Deployed Date: 1/28/2010		
Pre-Deployment On Deck Instrument Failures: None.		
Sensors/Equipment Lost at Sea: Anemometer snapped off during deployment.		
Sensors Damaged During Deployment: None.		
General Comments: Anemometer snapped off during deployment, it was replaced with a		

spare.

Buoy Site: 8S 170W, A	ATLAS	Mooring Depth: 5373 m		
Mooring Operation: F	Recovery	Mooring ID#: PM81:	5A	
Deployed Location: 0	8 00.20S 170 00.483W	Deployed Date: 5/28/	'09	
Recovered Location: (07 58.064N 170 00.90W	Recovered Date: 1/28/2010		
Previous Repair Date:	None			
Sensors/Equipment L	ost at Sea: None			
Sensors Damaged/Fou	lled: None			
Fishing/Vandalism: N	Vone			
Sensors/Tubes Not Do	wnloaded: All sensors	downloaded successfully	except Tube 439 – no	
communications.				
General Comments: 1	None.			
Site Sensor Failures	Site Sensor Failures Date Sensors Failed Why Sensors Failed Field Service			
			Observations	

Buoy Site: 5S 170W, ATLAS	Mooring Depth: 5417 m	
Mooring Operation: Visit	Mooring ID#: PM816A	
Deployed Location: 05 00.00S 169 59.583W	Deployed Date: 5/30/2009	
Visit Location: 04 59.5S 170 00.7W	Visit Date: 1/31/2010	
Previous Repair Date: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None.		
Fishing/Vandalism: None		
General Comments: Visit only. Buoy riding well in the water.		

Buoy Site: 5S 170W, Refresh	Mooring Depth: unk m	
Mooring Operation: Visit	Mooring ID#: DM001B	
Deployed Location: 04 58.30S 169 57.183W	Deployed Date: 1/23/2009	
Visit Location: 04 56.43S 169 57.48W	Visit Date: 1/31/2010	
Previous Repair Date: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None.		
Fishing/Vandalism: None		
General Comments: Visit only. Buoy position not determined by radar, ship position		
recorded	•	

Buoy Site: 2S 170W, ATLAS	Mooring Depth: 4962 m
Mooring Operation: Recovery	Mooring ID#: PM817B
Deployed Location: 02 09.90S 170 00.483W	Deployed Date: 5/31/09

Recovered Location: (covered Location: 02 08.40S 170 02.803W Recovered Date: 2/01/2010				
Previous Repair Date:	Previous Repair Date: None				
Sensors/Equipment Lo	ost at Sea: Wind Sensor	, SN 37781; T100: SN14	1675; T125, SN14676;		
T150, SN14677					
Sensors Damaged/Fou	iled: T250, SN14679 dro	opped on deck, case crac	ked.		
Fishing/Vandalism: T	ower in water, held by li	fting line			
Sensors/Tubes Not Downloaded: All sensors downloaded successfully except T250,					
SN14679, no communications.					
General Comments: Tower unbolted, three holes in buoy near eyelets. Fishing vessels					
nearby. Numerous cuts in nilspin from 50 to 125 m.					
Site Sensor Failures Date Sensors Failed Why Sensors Failed Field Service					
		-	Observations		

Buoy Site: 2S 170W, ATLAS	Mooring Depth: 4962 m	
Mooring Operation: Deployment	Mooring ID#: PM870A	
Deployed Location: 02 09.2S 170 00.9W	Deployed Date: 2/2/2010	
Pre-Deployment On Deck Instrument Failures: None.		
Sensors/Equipment Lost at Sea: None.		
Sensors Damaged During Deployment: None.		
General Comments: Routine deployment.		

Buoy Site: 2S 170W, Refresh	Mooring Depth: 4962 m	
Mooring Operation: Refresh Deployment	Mooring ID#: DM700A	
Deployed Location: 02 09.6S 170 02.7W	Deployed Date: 2/2/2010	
Pre-Deployment On Deck Instrument Failures:	25m T failed, replaced by PN 31296.	
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 00 170W, A	TLAS/CO2	Mooring Depth: 5602m		
Mooring Operation: F	on: Recovery Mooring ID#: PM764B			
Deployed Location: 0	Deployed Location: 00 00.40N 170 03.00W Deployed Date: 6/01/09			
Recovered Location: (Recovered Location: 00 02.009S 170 03.147W Recovered Date: 2/3/2010			
Previous Repair Date:	None			
Sensors/Equipment L	Sensors/Equipment Lost at Sea: TV 13m, SN13494.			
Sensors Damaged/Fouled: None.				
Fishing/Vandalism: Long-liner gear on nilspin.				
Sensors/Tubes Not Downloaded: All recovered sensors were successfully downloaded.				
General Comments: 2 sensor mounts broken and 2 poison pucks missing.				
Site Sensor Failures	sor Failures Date Sensors Failed Why Sensors Failed Field Service			
		-	Observations	

Buoy Site: 00 170W, ATLAS/CO2	Mooring Depth: 5609 m		
Mooring Operation: Deployment	Mooring ID#: PM871A		
Deployed Location: 01 01.298N 170 02.785W Deployed Date: 2/3/2010			
Pre-Deployment On Deck Instrument Failures: None.			
Sensors/Equipment Lost at Sea: None.			
Sensors Damaged During Deployment: None.			
General Comments: Nilspin not marked for 75 m sensor, estimated depth.			

Buoy Site: 2N 170W, A	ATLAS/CO2	Mooring Depth: 5387 m			
Mooring Operation: R	Recovery	Mooring ID#: PM765B			
Deployed Location: 0	ocation: 02 00.800N 170 01.083W				
Recovered Location: (covered Location: 02 00.714N 170 01.166W Recovered Date: 2/03/2010				
Previous Repair Date:	None				
Sensors/Equipment Lo	ost at Sea: T125, SN144	54; T150, SN12565			
Sensors Damaged/Fouled: None					
Fishing/Vandalism: Long liner gear wrapped around nilspin.					
Sensors/Tubes Not Downloaded: None.					
General Comments: Several sensor mounts broken, cuts in wire, and fishing line. Top puck					
missing on SSC.					
Site Sensor Failures	Site Sensor Failures Date Sensors Failed Why Sensors Failed Field Service				
			Observations		

Buoy Site: 2N 170W, ATLAS	Mooring Depth: 5387 m		
Mooring Operation: Deployment	Mooring ID#: PM872A		
Deployed Location: 02 00.90N 170 00.1W Deployed Date: 2/4/2010			
Pre-Deployment On Deck Instrument Failures: None.			
Sensors/Equipment Lost at Sea: None.			
Sensors Damaged During Deployment: None.			
General Comments: Mark at 300 m labeled as 400 m. Fathometer unreliable on fly-by, used			
previous deployment depth of 5387 m.			

Buoy Site: 5N 170W, ATLAS	Mooring Depth: 5667 m			
Mooring Operation: Visit/Repair	Mooring ID#: PM818B			
Deployed Location: 04 59.50N 169 58.383W	Deployed Date: 6/4/2009			
Visit Location: 05 00.40N 169 58.30W	Visit Date: 2/5/2010			
Previous Repair Date: None				
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: None.				

Fishing/Vandalism: None

General Comments: Replaced AT/RH SN58366 with SN118819 and downloaded data from tube.

Buoy Site: 8N 170W, ATLAS	Mooring Depth: 5665 m			
Mooring Operation: Visit	Mooring ID#: PM766A			
Deployed Location: 08 00.20N 170 00.617W	Deployed Date: 8/27/2008			
Visit Location: 08 00.054N 170 03.976W	Visit Date: 2/6/2010			
Previous Repair Date: None				
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: None.				
Fishing/Vandalism: None				
General Comments: Visit only. Buoy in good condition.				

Buoy Site: 8N 180, ATLAS	Mooring Depth: 3578 m			
Mooring Operation: Visit	Mooring ID#: PM819A			
Deployed Location: 07 59.60S 179 52.083W	Deployed Date: 6/8/2009			
Visit Location: 07 59.40S 179.52.9W	Visit Date: 2/8/2010			
Previous Repair Date: None.				
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: None.				
Fishing/Vandalism: None				
General Comments: Visit only. Buoy in good condition.				

Buoy Site: 8N 180, Refresh	Mooring Depth: 5854 m		
Mooring Operation: Visit	Mooring ID#: TM002A		
Deployed Location: 07 58.30N 179 53.6W	Deployed Date: 2/2/2009		
Visit Location: 07 57.50N 179 54.30W Visit Date: 2/8/2010			
Previous Repair Date: None			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: None.			
Fishing/Vandalism: None			
General Comments: Visit only. Buoy in good condition.			

2.2 <u>CTD Casts Completed</u>

A Sea-Bird 911plus CTD with dual temperature and conductivity sensors was provided by the NMAO. Temperature and conductivity sensors are calibrated yearly at Sea-Bird and sent in for diagnostics as necessary. A Sea-Bird 12-position carousel and twelve 5-liter Niskin bottles were used to collect water samples for the analysis of salinity.

After the eleventh CTD cast, the CTD winch controller had mechanical problems that could not be repaired at sea. Therefore, only 11 CTD casts were performed on this cruise.

The following outlines the CTD casts completed during the cruise:

CTD Operations					
Nominal Position	Date	Cast #	Comments		
8N 15W	1/9/10	KA011	3000 m		
7N 155W	1/10/10	KA021	1000 m		
6N 155w	1/10/10	KA031	1000 m		
5N 155W	1/11/10	KA041	1000 m		
4N 155W	1/11/10	KA051	1000 m		
3N 155W	1/11/10	KA061	1000 m		
2N 155W	1/12/10	KA071	1000 m		
1N 155W	1/12/10	KA081	1000 m		
0 155W	1/12/10	KA091	3000 m		
1S 155W	1/14/10	KA101	1000 m		
2S 155W	1/14/10	KA111	1000 m		
3S 155W	1/14/10	KA0121	1000 m		
4S 155W	1/15/10	KA0131	1000 m		
5S 155W	1/15/01	KA0141	1000 m		
6S 155W	1/16/10	KA0151	1000 m		
7S 155W	1/16/10	KA0161	1000 m		
8S155W	1/17/10	KA0171	3000 m		
8S 170W	1/28/10	KA0181	1000 m		
2S 170W	2/1/10	KA0192	1000 m		
0 170W	2/3/10	KA0202	1000 m		
2N 170W	2/4/10	KA0211	1000 m		
5N 170W	2/5/10	KA0221	1000 m		
6N 170W	2/5/10	KA0231	1000 m		
7N 170W	2/5/10	KA0241	1000 m		
8N 170W	2/6/10	KA0251	1000 m		
8N 180	2/8/10	KA0261	1000 m		

2.3 Ancillary Science Projects Completed on the Cruise

The following outlines the ancillary science work performed in conjunction with the TAO operations on the cruise:

Pacific Marine Environmental Laboratory (PMEL) Argo Profiling CTD Floats

Three Argo floats were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All Argo Float deployments were completed as scheduled.

Questions concerning ARGO Floats should be directed to:

Gregory Johnson, NOAA/PMEL or Elizabeth Steffen, NOAA/PMEL

Tel: (206) 526-6806 Tel: (206) 526-6747

E-mail: <u>pmel_floats@noaa.gov</u>
E-mail: <u>pmel_floats@noaa.gov</u>

The following outlines the Argo floats deployed during the cruise:

ARGO Floats				
Coor	rdinates	Date	SN#	Comments
00 01.791S	154 58.073W	1/13/10	4602	
00 00.804S	170 02.737W	2/3/10	4604	

Atlantic Oceanographic and Meteorological Laboratory (AMOL) Surface Drifting Floats

Twelve AOML Surface Drifters were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All AOML Surface Drifter deployments were completed as scheduled.

Questions concerning AOML Surface Drifters should be directed to:

Shaun Dolk, NOAA/AOML Global Drifter Center, Tel: (305) 361-4546

Fax: (305) 361-4436

E-mail: shaun.dolk@noaa.gov

The following outlines the AOML Drifting floats deployed during this cruise:

AOML Floats				
Coor	dinates	Date	SN#	Comments
04 58.953N	15 454.450W	1/11/10	90399	
03 01.067N	154 57.054W	1/11/10	90409	
00 02.274S	154 57.917W	1/13/10	90404	
02 59.842S	155 01.140W	1/15/10	90400	
04 58.873S	154 58.843W	1/16/10	90413	

04 57.449S	169 56.052W	1/31/10	90396	
03 00.281S	170 01.028W	2/1/10	90395	
00 00.798S	170 02.809W	2/3/10	90407	
02 59.849N	170 00.650W	2/4/10	90406	
05 02.125N	169 58.410W	2/5/10	90402	
04 57.449S	169 56.052W	1/31/10	90396	
03 00.281S	170 01.028W	2/1/10	90395	
00 00.798S	170 02.809W	2/3/10	90407	
02 59.849N	170 00.650W	2/4/10	90406	
05 02.125N	169 58.410W	2/5/10	90402	
04 57.449S	169 56.052W	1/31/10	90396	

PCO2 and Nitrate Mapping System and Nutrient Samples

Eleven (26) 30ml water samples were collected on this cruise. The chief scientist verified and briefed the Operations Officer on the specifications of the water samples to be collected during CTD casts prior to the start of the cruise. All water samples were collected as scheduled.

Questions concerning Nutrient Samples should be directed to:

Cathy Cosca NOAA/PMEL 7600 Sand Point Way NE Seattle, Washington 98115

Tel: (206) 526-6183

E-mail: cathy.cosca@noaa.gov